RG104 E-1 Box 179

Mem.

Mr Reichhelm's advice amounts to simply this, if anything is wrong with the tile pipe connected to my furnaces we can get it repaired, undoubtedly there are many men in Phila, who can repair the pipe or make much better. The Tinsmith employed in the Mint has repaired the pipes as well as he can without taking it all down and reports that air is entirely too thin. As I consider a large price was paid for this work this should not be the case - Chas E Barber Engr

NARA RG104, Entry 1, Box 179

Mem.

Mr. Reichhelm's advice amounts to simply this, if anything is wrong with the tin pipe connected to my furnaces we can get it repaired, undoubtedly there are many men in Phila., who can repair the pipe or make much better. The Tinsmith employed in the Mint has repaired the pipe as well as he can without taking it all down and reports that tin is entirely too thin. As I consider a large price was paid for this work this should not be the case.

Chas. E. Barber
Engraver